







## Replacement Parts


PPR75, PPR100, PPR125, PPR150, PPR200, PPR300, PPR400











**WARNING:** 3" and 4" fitting borers create a large reaction torque that can cause injury to operator. Use caution when using these tools. A standard 1/2", right angle drill is recommended.

**Note:** Carbide insert has four cutting edges. Change cutting edge by removing the cap screw and rotating the carbide 180° then reinsert cap screw and tighten.

Parts List				
		³⁄₄" - <b>1</b> "	1-1/4" - 4"	
Ref. No	. Description	Item Code	Item Code	Qty.
1	SHAFT	44525	44524	1
2	CARBIDE	24523	24524	1
3a	8-32 CAP SCREW	_	24525	1
3b	4-40 CAP SCREW	24522	_	1
4	1/4" - 20 SET SCREV	V 30087	30087	1

QUALITY
Service
that Last a Lifetime